MATERIAL SAFETY DATA SHEET

WOOD STAIN PROVINCIAL

Page:

1

#RODUCT NAME: WOOL STAIN PROVINCIAL

#RODUCT CODE: ⊍a cað

HMIS CODES: H F R P

1 2 0 D

MANUFACTURER'S NAME: LENGTO MEG. CORP. - ։ ԱՄՄ. ԹՐԱԿՄԸ #5 MDDRESS

SUN LURENZO, PULRTO RICO

18075A

: 736-4200 EMERGENCY PHONE

DATE PRINTED : CB/ 11/VIV

NAME OF PREPARER : MICHOR M. HERNANDEZ INFORMATION PHONE : (787) 736 4200

****====== SECTION II - HAZARDOUS INGREDIENTS/SARA III INFORMATION ========

MEPARTABLE COMPONENTS	CAS NUMBER	VAPOR PRESSURE		WEIGHT PERCENT	
P-PROPANOL	67- 63-0	33	68 F		
ACGIH TLV: 400 PPM, DTHER: 500 PPM ALIPHATIC SOLVENT	64742-88-7	ê	6 6		
DSHA PEL: 500 PPM, ACGIH .LV: 100 PPM, OTHER: N/A * ZIRCONILM 24% * CUBALTO 12%	125328-521 MIXTURE	10 1	25 G 77		
OSHA PEL: 500 PPM, ACGIH TL/: .00 PPM, OTHER: N/A					

₱ Indicates toxic chemical(s) subject to the reporting requirements of section 313 of Title III and of 40 CFR 372.

No information available.

#OILING RANGE: របស់ ជកម្ម ១២២ deg k SPECIFIC GRAVITY (H2O=1): បិ.មិរ UAPOR DENSITY: HEAVER BEAN AIR

EVAPORATION RATE: SLOWER HARM ETHER MATERIAL V.O.C.: 5.01 Large

COATING V.O.C.: D.G. 1D/gl

CLUBILITY IN WATER: NON SOLUBLE APPEARANCE AND ODOR: SOLVENT UDOR

FLASH POINT: 53 deg f

METHOD USED: TOO

FLAMMABLE LIMITS IN AIR BY VOLUME- LOWER: . 9

UPPER: _0.4

EXTINGUISHING MEDIA: TOAM, COL, DRY CHEMICAL, WATER FOR

SPECIAL FIREFIGHTING PROCEDURES

CONTAINERS COOL.

UNUSUAL FIRE AND EXPLOSION HAZARDS

MINTREMELY FLAMMABLE. VAPORS MAY IGNITE EXPLOSIVELY AND/OR CAUSE FLASH FIRES. ELIMINATE SDURCES OF IGNITION. NO SMOKING. USE ADEQUATE HURGOS VENTILATION SUFFICIENT .S REMOVE SDOR OF SOLVENT AND VAPORS.

BTABILITY: STABLL CONDITIONS TO AVOID

EXCESSIVE HEAT, POOR VENTILATION, CORROSIVE ATMOSPHERES, EXCESSIVE AGING.

ENCOMPATIBILITY (MATERIALS TO AVOID)

MATERIALS. ALKALINE MATERIALS.

MATERIAL SAFETY DATA SHEET

MOOD STAIN PROVINCIAL

Page: 8

MAZARDOUS DECOMPOSITION OR BYPRODUCTS

CARBON MONOXIDE, CARBON DIBXIDE, AND BXIDES OF NITROGEN.

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

***************** SECTION VI - HEALTH HAZARD DATA =================

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

ADUTE SIGS OF DVEREXPOSURE COULD BE HEADACHE, DIZZINESS NAUSEA, UPPER RESPIRATORY DRYNESS O IRRITATION, CAGWSINESS, MENT AL DEPRESSION OR MARCOSIS.

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE

EYE CONTACT: SEVERE IRRITATION, TEARING, REDNESS AND BLURRED VISION.

SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

SKING CONTACT: CAN DRY AND DEFAT SKIN CAUSING CROCKS, IRRITATION, AND DERMATITIS.

INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

INCESTION: CAN CAUSE GASTROINTESTINAL IRRITATION, VOMITING, NAUSEA, AND DIARRHEA.

HEALTH HAZARDS (ACUTE AND CHRONIC)

IMPLATION-DIZZYNESS, BREATHING DIFFICULTY, HEADACHES, & LOSS OF COORDINATION. EYE CONTACT-SEVERE TAXITATION, TERING, RED NESS, AND BALBRED VISION. SKIN CONTACT- CAN DRY AND DEFAT SKING CAUSING CRACKS, TARITATION AND DERMITITIS. INGESTION-CAN CAUSE GASTRDINTESTINGL TRRITATION. VONITING NAUSSER, & DIARRHER, NO CHRONIC HEALTH EFFECTS.

CARCINOGENICITY: NTP CARCINOGEN: No IARC MONOGRAPHS: 146 OSHA REGULATED: No MONE

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE MESTICSIA. RESPIRATORY (RAC. IRRITATION, DERMITTITIS, NAUSEA, VOMITTING.

EMERGENCY AND FIRST AID PROCEDURES

IMPLATION OVEREXPOSURE - KOVE PERSON TO FRESH AIR. IF BREATHING STOPS, APPLY ARTIFICIAL RESPIRATION AND SEEX IMMEDIATE MEDICAL ATENTION. EYE CONTACT- FLUSHWITH LARGE QUANTITIES OF WATER FOR 15 MINUTES. SKIN CONTACT- WASH THOROUGHLY WITH SOAP AND WATER AND SEE A SOCTOR. INGESTION DO NOT INDUCE YOUTHING, CAN CAUSE CHEMICAL PHEUMONITIS AND PULMONARY EDEMA. CONTACT PHYSICAL IMMEDIATELY.

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

ELIMINATE IGNITION STURCES, PROVIDE 6000 VENTICATION, DIKE SPILL AREA ADD ABSORBENT EARTH OR SAWDUST TO SPICLED LIGUID. TH**OROGALY MET**W/ MATER AND MIX.

WASTE DISPOSAL METHOD

COLLECT ABSORBENT/ WATER/ SFILLED LIQUID MIXIBRE INTO METAL CONTAINERS AND ADD ENOUGH WATER TO COVER. CONSULT LOCAL, STA TE & FEDERAL HAZARDOUS WASTE REGULATION REFORE DISPOSING INTO APPROVED HAZARDOUS WASTED LANDFILLS. OBEY RELEVANT LAW.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

KEEP CONTAINERS CLOSED WHEN NOT IN USE. STORE 60-95 F OUT OF SUN. USE ADEQUATED VENTILATION TO AVOID SMEATHING VAPOR WHE N COVER REMOVED. KEEP AWAY EXESSIVE MEAT AND OPEN FLAMES.

OTHER PRECAUTIONS

MINDO ALL EQUIPMENT WHEN HANDLING FLAMMABLE SOLVENT BORNE MATERIALS. SMOKING IN AREA WHERE THIS MATERIAL IS USED SHOULD BE STRICTLY PROHIBITED.

RESPIRATORY PROTECTION

INTEN SPRAYING THIS MATERIAL USE A NIDSH APPROVED CARTRIDGE RESPIRATOR OR GAS MASK SUITABLE TO KEEP AIRBORNE MISTS AND VA POR

MATERIAL SAFETY DATA SHEET

MOOD STAIN PROVINCIAL

Page:

3

CONCENTRATIONS BELOW THE TIME WEIGHTED THRESHOLD LIMIT VALUES. WHEN USING IN POORLY VENTILATED AND CONFINED SPACES, USE A FRESH-AIR EMPLYING RESPIRATOR OR A SELS- CONTAINED BREATHING APPARATUS.

WENT I ATTON

**FICIENT TO KEEP WORKEGOM CONCENTRATION BELOW TLV. VENTILATION EQUIP. MUST BE EXLPOSION PROOF.

PROTECTIVE GLOVES

CHEMICALS RESISTANT GLOVES.

EYE PROTECTION

WEEK CHEMICAL SAFETY GLASSES, GOGGLES, AND FACESHIELDS FOR EYE PROTECTION.

DTHER PROTECTIVE CLOTHING OR EQUIPMENT

WORK/HYGIENIC PRACTICES

EVE MASHES AND SAFETY SHOWERS IN THE WORKPLACE IS RECOMMENDED.

the information contained herein is based on data believed by this company to be accurate, but we do not assume any limiting for its rewrited. We neither suggest not guarantee that any hazards mentioned are the only ones which exist. The manner of that use and which exist is any infringement of patents is the sole responsibility of the user.